

IMPORTANT SAFETY RECALL

RALEIGH 2007 CADENTS CADENT 1.0 - CADENT2.0 - CADENT CARBON

FORK MAY FAIL CAUSING RIDER TO LOSE CONTROL OF
THE BICYCLE, FALL, AND SUFFER SERIOUS INJURY



CADENT CARBON



CADENT 2.0



CADENT 1.0

Stop using your bike immediately and return it to any Raleigh Dealer for a replacement fork.

Please contact us at: (888)805-6396

Raleigh America Inc.. - 6004 S. 190th Street, Suite 101, Kent, WA 98032

In cooperation with the U.S. Consumer Product Safety Commission
Post Unit#: 01/31/2008